



One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038 U.S.A.
(920) 699 2000
Fax: (920) 699 6836

Product Safety Recall Notice Rev 1: BOB-CAT PROCAT/PREDATOR PRO Mowers and Mowers with SEAT KIT 970522. This revision updates the customer letter sent to the purchasers of Bob-Cat models with the serial numbers indicated below that are not highlighted on dated November 30, 2016, a copy of which is attached. This revision updates that letter by providing additional serial numbers for Bob-Cat ProCat and Predator Pro models 942532 & 942533 as highlighted below in yellow that are now part of this Recall. You are receiving these letters since our records indicate you own one of these mowers.

December 15, 2016

Dear **BOB-CAT** Customer,

Schiller Grounds Care (manufacturer of BOB-CAT branded mowers) is conducting a voluntary recall on BOB-CAT ProCat and Predator Pro mowers with serial numbers in the ranges identified below and BOB-CAT mowers that have had Seat Kit 970522 installed. Our records indicate that you may own one of these mowers.

Is your mower affected?

The BOB-CAT ProCat and Predator Pro Models listed below may be affected:

Model	Serial range	Model	Serial range
942529	00198-00210	942532CA	00070-00101
942532	00100-00852	942532K	00900-01017
942533	00100-01212	942533CA	00070-00103
942509K	00300-00313	942533K	01300-01760
942514J	01370-01602	942534J	00100-00267
942514K	01700-01936	942534K	00300-00454
942515J	00462-00519	942535J	00100-00207
942515K	00600-00618	942535K	00300-00347
942516J	00306-00319	942536J	00100-00107
942516K	00400-00404	942536K	00200-00211
942519J	00326-00401	942537J	00100-00115
942519K	00500-00598	942537K	00200-00231
942529K	00300-00355	942538K	00070-00074

These are actual serial numbers not a range -

942539K 94253900070 and 94253900071
942540K 94254000070 and 94254000076
942541K 94254100071, 94254100072 and 94254100077

If you have installed **Seat Kit 970522**, on any other BOB-CAT model, that mower is also affected.

What is the problem?

The seat belt holder utilized on the ProCat and Predator-Pro models listed above and in Kit 970522 may rub against the gas tank in certain driving conditions. Over time this may wear a hole into the gas tank side wall causing the gas tank to leak.



One BOB-CAT Lane, P.O. Box 469
Johnson Creek, WI 53038 U.S.A.
(920) 699 2000
Fax: (920) 699 6836

What should you do?

Immediately STOP USING YOUR MOWER until it has been repaired. Please contact your authorized BOB-CAT equipment dealer to make an appointment to have kit **(4174284)** installed free of charge. Service kits to repair these units are being made available to BOB-CAT dealers.

Who to contact if you have question or experience problems:

If you have any questions or if you are not satisfied with the service you receive from your BOB-CAT Equipment dealer, you may call 866-469-1242 toll-free between 8:00 a.m. and 5:00 p.m. CT, Monday to Friday; write to the address below or go to www.bobcatturf.com and click on Product Recall Information at the bottom of the page for more information.

Schiller Grounds Care, Inc.
One Bob-Cat Lane
Johnson Creek, WI 53038

If you have sold your mower, please pass this information along to the new owner.

What to do if you feel this notice is in error:

This notice was mailed to you according to the most current information we have available. If you no longer own this mower or some information in this notice is incorrect, please contact us at 866-469-1242. Please have your mower's serial number and the complete address of the person who purchased your mower available. This will help us to update our records. We thank you for your purchase of a BOB-CAT Mower and apologize for any inconvenience this situation may cause.

Sincerely,

BOB-CAT Customer Service